

Insurance Projects, Nationwide

The Curley Group stands as a trusted entity within the realm of insurance, having forged strong partnerships with esteemed organisations like Direct Line, AXA, and Allianz. Through a proven track record of service excellence and a commitment to delivering unparalleled solutions, the Curley Group has established itself as a reliable ally for insurance providers seeking expertise and innovation. With a history of collaboration with industry giants, their expertise extends beyond conventional boundaries, ensuring a comprehensive approach to navigating the dynamic landscape of construction.

Client	Direct Line, AXA, Allianz
Date	2018 – 2024
Project Categories & Value	
General Claims	Up to £15,000.00
Subsidence Claims	Up to – £500,000
Major Loss Claims	Up to £1,500,000.00



Scope of works

The Curley Group has garnered a commendable reputation by securing contracts with diverse insurance companies, wherein they seamlessly handle multifaceted tasks. Their expertise extends across various domains, and they have successfully entered three distinctive frameworks tailored for insurance companies. These encompass General Claims, covering values up to £15,000.00, Subsidence Claims with a cap at £500,000.00, and Major Claims with a substantial value of up to £1,500,000.00. What sets the Curley Group apart is their ability to provide an end-to-end solution as a sole contractor, leveraging their extensive services in the construction sector.

As a sole contractor, the Curley Group tackles each project with a comprehensive approach, addressing specific challenges that arise, particularly when working within 'live' environments for businesses or private clients. The nature of these projects demands meticulous care and personalised management to instil confidence and peace of mind in their clientele.

In addition to their project-oriented endeavours, The Curley Group extends its commitment further by providing a 24-hour emergency call-out service tailored specifically for insurance companies. This round-the-clock availability underscores their dedication to swift and efficient responses, ensuring that urgent situations are met with immediate and effective solutions. The combination of their comprehensive project management and emergency services solidifies The Curley Group's standing as a versatile and reliable partner within the insurance industry.



General Claims

The Curley Group was summoned to provide support to the fire brigade during an emergency situation in Lytham St Annes. A vehicle had collided with a garage, resulting in significant structural damage to the building. In a collaborative effort with the fire brigade, The Curley Group played a crucial role in stabilizing the compromised structure, allowing for the safe removal of the vehicle from the scene.

Over the ensuing weeks, The Curley Group successfully executed a comprehensive range of tasks to restore the damaged property. These included the temporary propping of the roof, removal of compromised brickwork, systematic stripping of the roof, salvage of usable materials, meticulous rebuilding of brickwork piers, installation of new load-bearing lintels, fitting of new garage doors, replacement of salvaged roof tiles, internal restoration, and the application of a fresh coat of paint to the garage floor.

This concerted effort not only addressed the immediate challenges posed by the emergency but also resulted in the thorough rehabilitation of the affected structure. The Curley Group's expertise and timely response played a pivotal role in mitigating the impact of the incident and restoring the damaged property to its pre-incident condition.





CURLEY GROUP



The Curley Group Ltd. Co. Reg. 13143071



Subsidence Claims

Cockermouth, Cumbria

The Curley Group undertook the challenging task of addressing a subsidence claim in Cockermouth, Cumbria. The property in question was situated precariously on a cliff face, and over time, the erosion and deterioration of the cliff face had rendered the house unstable. To rectify this issue, a comprehensive series of measures were implemented.

Initially, the team demolished the kitchen extension to pave the way for subsequent interventions. Stabilising anchors were strategically inserted into the rock face, addressing the core instability of the property. However, the complexity of the project required further steps, necessitating the installation of foundations at the base of the cliff, a staggering 30 meters below the property's original location. Additionally, a formidable retaining wall, constructed in sections and towering 30 meters high, was erected to fortify the cliff face and provide structural support.





CURLEY GROUP



The Curley Group Ltd. Co. Reg. 13143071





CURLEY GROUP

Following the completion of these foundational tasks, the project moved on to the meticulous process of rebuilding the house extension. This phase involved not only reconstructing the physical structure but also incorporating modern engineering techniques to ensure long-term stability.

The project, though technically demanding, was further complicated by adverse weather conditions prevalent in the region. The harsh weather posed a continuous challenge throughout the construction process, requiring the team to adapt and implement specialized measures to counteract its effects.

Moreover, the logistics of the project were inherently intricate due to the remote location of the property. Transporting materials, coordinating deliveries, and managing the workforce in such a secluded environment demanded meticulous planning and execution. Overcoming these logistical hurdles underscored the Curley Group's commitment to delivering a successful resolution to the subsidence claim, showcasing their expertise in navigating complex construction projects under challenging circumstances.



The Curley Group Ltd. Co. Reg. 13143071







Major Loss Claims

Logistics Warehouse, Salford

The Curley Group swiftly responded to an urgent call from Direct Line, mobilising for an emergency situation involving a weather-damaged property. Upon reaching the site, our team took immediate action to secure the area, ensuring the safety of the public by dismantling the unstable brickwork. As the extent of the damage became apparent, the scope of the remedial work escalated, falling within the major loss framework.



Under our mandate, The Curley Group assumed the responsibility of evaluating the structural integrity of the affected building. To bring specialized expertise into the equation, we enlisted the services of a seasoned structural engineer. Their comprehensive assessment revealed a high-risk scenario, necessitating the demolition of both brick and block components, along with the removal and replacement of the five steel frame stanchions. Our commitment to meticulous evaluation and decisive action underscores The Curley Group's dedication to ensuring the security and stability of properties under our care.

